

METHOD FOR CONTROLLING A BURNISH CYCLE TO MINIMIZE CYCLE TIME

ABSTRACT

A method for controlling a burnish cycle to minimize cycle time is disclosed.

- 5 MR sensor resistance measurements are used to monitor interference with the recording surface and when clearance is not detected, steps are taken to fine tune the interference signal.